

R04再現図採点結果

2023/2/5

NO	ランク	0	1	2	3	4	5	6	7	8	9	減点	点数	失格	コア位置	スパン	階高さ	アプローチ	屋上庭園	備考
1	1			4	2					3	5	14	86		-	8	4.0	S	↘	コアセンター合格
2	1	2		2	2		1	1		4	3	15	85		-	15	4.0	S	→	
3	1			3	5		1	1		3	2	15	85		-	14	4.0	S	→	
4	1			2	3	1	2			4	3	15	85		-	14	4.0	S	→	
5	1	1	1	3	2		5			2	1	15	85		-	12	4.0	S	↓	
6	1		1	2	1		3	1		3	5	16	84		-	16	4.0	S	→	
7	1			4	1		2	1		3	5	16	84		-	16	4.0	S	↑	
8	1		1	3	9					2	3	18	82		-	16	4.0	S	→	
9	1		2	2	8	1		2	1	2	2	20	80		-	14	4.0	S	→	
10	1			4	6		5			1	5	21	79	○	-	14	4.0	S	→	○特抜け再現ミスか。
11	1		1	2	6	1		1	3	4	4	22	78			12	4.0	Sn	↙	かなり特異だが減点少なめ
12	1		3	2	7			1	4		5	22	78		-	14	4.0	S	↘	
13	1		3	3	3			2		3	10	24	76	○		16	4.2	S	↓	切断方向間違い・・・。
14	1			2	6	1	5			2	12	28	72		-	16	4.0	S	↘	
15	1		1	4	7		6			4	6	28	72	○	-	12	4.0	S	→	貸事務室有柱、1最低点
16	2		1	2	11					2	5	21	79		-	8	4.0	S	↓	2 最高点 減点不合格
17	2	2	8	4	4	1				6	10	35	65		-	14	4.0	S	→	減点不合格
18	3		1	2	1	3				2	1	10	90		-	8	4.0	Ns	→	3 最高点・北入・コアPC・プラン
19	3	1	1	4		1	4				6	17	83	○	-	16	4.2	S	↓	基礎梁なし
20	3		2	2	9		1	1		4	6	25	75		-	16	4.0	SN	→	断面寸法抜け・キュービクル抜け
21	3			3	6					6	10	25	75		-	16	3.9	S	→	EV3基・天井高さ
22	3			4	6		3	1		2	10	26	74		-	9	4.0	S	↑	北向き・・・
23	3	2		2	9		1			6	7	27	73		-	15	4.2	S	→	階段踏面足らず・基礎×
24	3	1	2	4	4	3		1	1	5	6	27	73	○		14	4.2	N	→	EV1基+1基
25	3		4		6	9	3	2	0	3	2	29	71	○	-	12	4.0	S	→	3,000m2足りず
26	3	2	1	2	8	1	3	1		9	4	31	69	○	-	15	4.0	S	→	延焼ラインアウト
27	3		5	4	4		1	1	3	5	10	33	67		-	16	4.0	S	↓	EV3基・屋上庭園上部構造
28	3	1	3	3	11			3	1	4	10	36	64		-	15	4.0	S	→	減点不合格
29	3	2	6		8	1	6		1	9	4	37	63	○	-	16	4.0	S	→	減点不合格
30	3	1	6	4	11		1		2	7	6	38	62		□	9	4.0	Sn	→	減点不合格
31	3	2		2	13	6	2	1		8	5	39	61		-	9	4.0	S	→	減点不合格
32	3	2	8	4	12		1	1	3	7	4	42	58		-	15	4.5	S	→	減点不合格
33	3	2	9	4	11		1	1		5	10	43	57		-	9	4.0	S	→	減点不合格
34	3	5	4	3	10	1	6	2		12	1	44	56	○		12	4.0	S	↓	減点不合格
35	3	3	5	2	16	6	11	3	3	3	14	66	34	○	-	14	4.0	S	↓	減点不合格
36	4			4		1	7			1	8	21	79	○	-	15	4.0	S	→	4 最高点・無窓二方向×
37	4		3	2	10	1	3	1		1	5	26	74		-	16	4.0	S	→	屋上キュービクル×
38	4		2	3	1		2	3	2	5	8	26	74	○	-	16	4.0	S	→	陸立柱
39	4	1	1	2	3		5	3		4	7	26	74	○		17	4.2	Sn	↑	延焼ラインアウト
40	4		7	4	7		1			5	7	31	69	○		12	4.0	S	→	3,000m2足りず
41	4		2	3	10	1	4		2	5	5	32	68	○	-	16	4.0	S	↑	無窓二方向
42	4		5	2	11	2	1	2		7	3	33	67		-	8	4.0	S	→	駐輪場抜け
43	4	2	1	7	5		3	4	1	5	6	34	66	○		12	4.0	S	↑	EV○特抜け
44	4	2	2	2	10	3	4	1		6	4	34	66	○	-	16	4.0	S	↙	貸事務室柱3本
45	4	4	3	4	9		2	5		3	10	40	60	○		11	4.5	SN	→	階段非対応
46	4	3	8	2	9	3	3	2		8	10	48	52	○	-	9	4.0	SN	↗	未完扱い
47	4		5	2	20		3	2		6	10	48	52	○	□	14	4.0	S	↓	二方向避難抜け
48	4	2	5	4	7	3	11	1	1	5	10	49	51	○		12	4.0	S	→	貸事務室B柱2本
49	4	1	4	3	9	4	8	4	3	5	11	52	48	○	-	12	4.0	S	↓	3,000m2足りず
50	4	3	4	3	11	2	6	3	7	10	9	58	42	○	-	18	4.0	S	↓	陸立柱・ロングスパン
51	4	3	3	3	19		10	2	3	8	10	61	39	○		12	5.0	S	↓	未完扱い
52	4	1	1	3	18		9	4	3	12	13	64	36	○		16	4.5	SN	→	延焼ライン? 構造不成立
全52枚		1.0	2.6	2.9	7.4	1.1	3.0	1.3	0.8	4.6	6.5	31.2	68.8	25人						